OIPE
JUN 24 2003
PATENT & TRADEMARK OFFICE
JC48



FIG 1

OIPE
JUN 24 2003
PATENT & TRADEMARK OFFICE
JC48



FIG 2



FIG 3



FIG 4



FIG 5

OIPE JC48 JUN 24 2003 PATENT & TRADEMARK OFFICE



Six Measurements Obtained

Fa(high) High
Fa (low) Low
Fb(high)
Fb(low)

FIG 6

F high = Fa(high)/Fb(high)

F low = Fa(low)/Fb(low)

t* = [ln (F high) - ln (F low)]/(High - Low)

FIG 7

MAP OF FRACTURED ZONE



FIG 8



PATENT & TRADEMARK OFFICE
JUN 24 2003
JC48



OIPE JC4 8
JUN 24 2003
PATENT & TRADEMARK OFFICE



FIG. !!